

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S4	1	"20050044278".pn.	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/18 16:18
S5	5	active near5 firmware near5 update	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 12:30
S6	5	active near5 firmware near5 updat\$3	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 12:33
S7	7	active near5 firmware near5 (updat\$3 upgrad\$3)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 12:35
S8	2	S7 not S6	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 12:33
S9	15106	(firmware code) near5 (updat\$3 upgrad\$3)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 12:35
S10	201	(firmware code) near5 (updat\$3 upgrad\$3) with active	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 12:45
S11	57	S10 and disrupt\$3	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 12:48
S12	22	S10 and disrupt\$3 near5 (operation function\$3)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 12:36

S13	1371	(firmware code memory) near5 (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) with active	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 15:12
S14	36	S11 and (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) same (disrupt\$3 interfer\$3 interrupt\$3)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 13:08
S15	1094	(updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) with (drive near3 reset\$4 reboot\$3)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 13:09
S16	1402	(firmware code memory rom read\$1only\$1memory eeprom flash) near5 (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) with active	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 16:46
S17	162	S16 and drive near5 (active normal operat\$3 function\$3)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 16:47
S18	5728	(firmware code memory rom read\$1only\$1memory eeprom flash) near5 (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) and ((updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) with active)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 17:10
S19	757	S18 and drive near5 (active normal operat\$3 function\$3)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 17:10
S20	5147	710/5,8.ccls. 711/100,103.ccls. 717/168,173,174.ccls.	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 16:50
S21	23	S20 and S19	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 17:11
S22	1	("6675258").URPN.	USPAT	OR	ON	2005/04/13 16:56
S23	5	("5848230" "6065096" "6085332" "6085333" "6446153").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/13 16:58

S24	306	S19 and (activat\$3 run\$4 updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) near4 (reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 17:11
S25	6390	(firmware code instruction memory rom read\$1only\$1memory eeprom flash) near5 (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) and ((updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) with active)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:25
S26	757	S19 and drive near5 (active normal operat\$3 function\$3)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 17:10
S27	793	S25 and drive near5 (active normal operat\$3 function\$3)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 17:10
S28	23	S20 and S27	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 17:11
S29	321	S27 and (activat\$3 run\$4 updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) near4 (reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 17:14
S30	179	S29 and (firmware code instruction memory rom read\$1only\$1memory eeprom flash) with (activat\$3 run\$4 updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) with (reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 13:03
S31	55	S29 and (firmware code instruction memory rom read\$1only\$1memory eeprom flash) near5 (activat\$3 run\$4 updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) near5 (reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/13 17:14

S32	22	(firmware code instruction memory rom read\$1only\$1memory eeprom flash)with seamless near4 (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 10:24
S33	4	"6266736".pn. "20040133888".pn.	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 10:08
S34	22	"5,210,854".pn. "6,101,327".pn. "6,463,584".pn. "20030051235".pn. "5,432,927".pn. "20040255293".pn. "20020170052".pn. "20030066065".pn. "20030018964".pn. "5,870,611".pn. "5,867,713".pn.	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 10:23
S35	190388	(firmware code instruction memory rom read\$1only\$1memory eeprom flash)with(updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:14
S36	597	S35 with transparent\$2	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 10:24
S37	5155	710/5,8.ccls. 711/100,103.ccls. 717/168,173,174.ccls.	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 10:25
S38	13	S36 and S37	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 10:25
S39	10	("5732275" "5764992" "6044442" "6151643" "6167567" "6237091" "6253281" "6266736" "6304798" "6519678").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/14 10:26
S40	28	S36 and (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) near4 (reset\$3 power)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 11:04
S41	0	("6782448").URPN.	USPAT	OR	ON	2005/04/14 10:41

S42	10	("5732275" "5764992" "6044442" "6151643" "6167567" "6237091" "6253281" "6266736" "6304798" "6519678").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/14 10:41
S43	51	S36 and (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) near4(reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 11:16
S44	23	S43 not S40	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 11:05
S45	67116	(updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) near4(reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:13
S46	12489	S35 and S45	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 11:17
S47	319	S46 and S37	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 11:17
S48	27512	(updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) near4(transparent\$2 seamless\$2 disrupt\$3 interfer\$3 interrupt\$3 disturb\$6)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 11:18
S49	81	S47 and S48	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 11:18
S50	10	("5732275" "5764992" "6044442" "6151643" "6167567" "6237091" "6253281" "6266736" "6304798" "6519678").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/14 12:05
S51	43247	(reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$) adj5 (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:14

S52	8675	S35 and S51	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:14
S53	1816	S52 and (detect\$3 determining) near3 (reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:16
S54	668	S53 and (detect\$3 determining) near3 (reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$) same (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:22
S55	17	S37 and S54	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:18
S56	328	S53 and (detect\$3 determining) near3 (reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$) with (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:23
S57	204	S53 and (detect\$3 determining) near3 (reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$)adj10 (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:23
S58	162	S53 and (detect\$3 determining) near3 (reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$)adj5 (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:41
S59	119	S58 and ((updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) with (active normal operat\$3 function\$3))	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:41
S60	118	S53 and (detect\$3 determining) adj3 (reset\$4 reboot\$3 re\$1start\$3 power\$3 turn\$)adj5 (updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4)	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:41
S61	97	S59 and ((updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) near5 (active normal operat\$3 function\$3))	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:42

S62	89	S59 and ((updat\$5 upgrad\$4 modif\$8 patch\$4 alter\$4) near3 (active normal operat\$3 function\$3))	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 12:42
S63	0	("6754895").URPN.	USPAT	OR	ON	2005/04/14 12:48
S64	275	S51 and S37	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 13:03
S65	5	S59 and S37	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 13:03
S66	22	"20020073413".pn. "20030163508".pn. "5,974,544".pn. "6,073,232".pn. "6317,815".pn. "6,356,977".pn. "6,363,457".pn. S33 "560,703".pn.	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 13:21
S67	16	"20020073413".pn. "20030163508".pn. "5974544".pn. "6073232".pn. "6317815".pn. "6356977".pn. "6363457".pn. "6560703".pn.	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/14 13:22
S68	7	("5388267" "5933631" "5940627" "5974567" "6009497" "6018629" "6018747").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/14 13:22
S69	197	power adj cycle near3 reset	US-PGPUB; USPAT; EPO; DERWENT; IBM_TDB	OR	ON	2005/04/18 16:19